High-Precision Tuning Fork Electronic Balance

AJ-NT/DBNT Series

Operation Manual

IMPORTANT

- To ensure safe and proper use of the balance, please read this manual carefully.
- After reading this manual, store it in a safe place near the balance, so you can review it as needed.



PREFACE

Thank you for purchasing an AJ Series electronic balance. This is a precision instrument equipped with exacting mechanisms in a compact body. The AJ series provides enhanced functions, including a counting mode for stock control of parts, and a limit function for measuring constant quantities by consecutive weighings. Despite its many functions, the balance is easy to operate and features user-friendly keys. Furthermore, the large liquid-crystal display provides excellent visibility, and the instrument's high speed and stability–intrinsic to a tuning fork design–help boost operational efficiency.

Before using the balance, please check that the following items have been included in the package.

Should you find any missing parts, please contact our local dealer.

(1) Main unit of balance



(2) Measurement pan (one round or square pan)





(3) Pan base (one small for the round-pan balance; one large for the square-pan balance)




(4) Windshield (one for round-pan balance only)



(5) AC adapter (one)



(6) DIN5P plug set



(7) Operation manual (one)



CONTENTS

1. Pr	recautions on the Use2	9. Input/output functions31
1.1	Warnings regarding Use2	9.1 Terminal Numbers and Functions31
1.2	For More Precise Measurements 5	9.2 Connection between Balances and
2. Na	ames of Component Parts8	Personal Computers32
2.1	Main Unit 8	9.3 Interface Specifications33
2.2	LCD Indicators and Operating	9.4 Output Data34
	Keys 9	9.5 Input Commands36
3. Ba	asic Operations11	10. Operating the Balance with the
3.1	Installation11	Battery38
3.2	Operation Check13	10.1 Specifications38
3.3	Operation for Zero Adjustment 14	10.2 Charging Method38
4. Fu	unctions16	10.3 User Precautions38
4.1	Setup and Checking of Functions 16	11. Operating the Balance with the
4.2	Description of Functions17	Dry Cell Battery (DBNT)39
4.3	Interface Section 18	12. Troubleshooting40
5. Sv	witching Function for	13. Specifications41
5. Sv	witching Function for Unit of Measurement 19	13. Specifications 41 13.1 Basic Specifications 41
5. S v	_	
	Unit of Measurement 19	13.1 Basic Specifications41
5.1 5.2	Unit of Measurement 19 Switching Units of Measurement. 19	13.1 Basic Specifications41 13.2 Common Specifications42
5.1 5.2	Unit of Measurement 19 Switching Units of Measurement . 19 Setup of Units of Measurement . 19	13.1 Basic Specifications
5.1 5.2 6. C 6	Unit of Measurement 19 Switching Units of Measurement . 19 Setup of Units of Measurement . 19 Dunting Pieces	13.1 Basic Specifications
5.1 5.2 6. Co 6.1	Unit of Measurement 19 Switching Units of Measurement . 19 Setup of Units of Measurement . 19 Dunting Pieces	13.1 Basic Specifications
5.1 5.2 6. Co 6.1 6.2	Unit of Measurement 19 Switching Units of Measurement . 19 Setup of Units of Measurement . 19 Dunting Pieces	13.1 Basic Specifications
5.1 5.2 6. Co 6.1 6.2	Unit of Measurement 19 Switching Units of Measurement . 19 Setup of Units of Measurement . 19 Dunting Pieces	13.1 Basic Specifications
5.1 5.2 6. Co 6.1 6.2	Unit of Measurement 19 Switching Units of Measurement . 19 Setup of Units of Measurement . 19 Dunting Pieces	13.1 Basic Specifications
5.1 5.2 6. Co 6.1 6.2 7. Mo 8. Li	Unit of Measurement 19 Switching Units of Measurement . 19 Setup of Units of Measurement . 19 Dunting Pieces	13.1 Basic Specifications
5.1 5.2 6. Co 6.1 6.2 7. Mo 8. Li 8.1	Unit of Measurement 19 Switching Units of Measurement . 19 Setup of Units of Measurement . 19 Dunting Pieces	13.1 Basic Specifications
5.1 5.2 6. Co 6.1 6.2 7. Mo 8. Li 8.1	Unit of Measurement 19 Switching Units of Measurement . 19 Setup of Units of Measurement . 19 Dunting Pieces	13.1 Basic Specifications

1. Precautions on the Use

1.1 Warnings regarding Use

- This Section "Precautions Relating to Use" sets forth precautionary notes that the user should observe in order to prevent physical injury to the user and/or damage to property.
- The nature of problems that may result in the event of improper operation, and consequential
 effects on the quality and performance of the balance, are indicated under the two categories of
 "Caution" and "Recommended," and explained using symbols.



This symbol indicates a risk of injury or property damage if the balance is used improperly. Be sure to observe these notes to ensure safe use of the balance as the improper use may cause serious results.

RECOMMENDED

This term indicates steps that the user should take to ensure the quality and reliability of the balance.

Meanings of Symbols Each symbol is accompanied by an instruction.



Indicates a "mandatory" action that should be executed without fail.



Mandatory Symbol:



Indicates a "prohibited" action that must not be executed.









- ◆ Do not disassemble or modify the unit.
 - Could cause malfunction or heat generation
 - · Contact our local dealer.





- ♦ Only AC power (rated value) should be used.
- Only use the dedicated AC adapter.
 - Use of other types of power or adapters may result in heat generation or malfunction of the balance.





- Do not move the balance when a sample is loaded.
 - The loaded sample may fall off the measurement pan and cause an injury.





- Do not place the balance on an unstable base or use the balance in a location where it may be subjected to shock.
 - The loaded sample may fall off the measurement pan.
 - Accurate measurement may be rendered impossible.





- ♦ Do not lay the AC adapter cable on the surface of the passage.
 - Somebody may trip on the cable, causing the balance to fall off, thereby causing injury and/or damage to the balance.





- ◆ Do not touch the AC adapter or balance with wet hands.
 - Danger of electric shock





- Do not use the balance in a location were it may be subjected to excess moisture.
 - Electric shock or short-circuiting could occur.
 - The balance may be corroded, with resultant malfunction.





- Do not use the balance with its adjusters lifted.
 - The balance will become unstable, preventing accurate measurement.





- ◆ Do not use the balance in a location where it may be subjected to excess dust.
 - Risk of explosion or fire
 - Short-circuit or lack of continuity may occur, leading to a malfunction of the balance.

RECOMMENDED





 Avoid applying excess force or impact to the balance.

Place the sample to be measured on the balance carefully to prevent breakage or malfunction.





- Do not use the balance in a location were it may be subjected to abrupt changes in ambient temperature or humidity.
 - Accurate measurement may not be obtained.
 - Optimum operations occur when ambient





- ◆ Do not use the balance when [o-Err] (Overloaded) is displayed.
 - Take down the loaded sample immediately to prevent breakage or malfunction.





- ◆ Do not use the balance in a location where it is subject to direct sunlight.
 - The indications would be illegible.
 - An internal temperature increase in the balance may lead to inaccurate measurement.





- ♦ If the balance is to be unused for an extended period of time, unplug the adapter.
 - This conserves power and prevents deterioration.





- ◆ Do not use volatile solvents for cleaning.
 - The body may be distorted.
 - To clean the unit of stains, use a piece of dry cloth or cloth soaked in a small quantity of neutral detergent.





- Do not use the balance in a location where it may be subject to air from an air-conditioning unit.
 - Extreme changes in the ambient temperature may result in inaccurate measurements.





- ◆ Do not use the balance on a soft floor.
 - When loaded with a sample, the balance may tip or move, preventing accurate measurements from being conducted.






- ◆ Do not use the balance when it is tilted.
- ◆ An inclined balance is likely to produce errors, preventing accurate measurements from being conducted. Place the balance on a level surface.

1.2 For More Precise Measurements

To be able to conduct more precise measurements, it is necessary to minimize the factors that contribute to measurement errors. There are a great variety of such error-inducting factors, which can be linked to machine error and performance of the balance itself, as well as the properties and condition of samples being measured, and the measuring environment (e.g., vibration, temperature/humidity). These factors can readily affect the results of measurement on a balance that has high resolution readability.

This material includes some precautionary notes that the user should bear in mind to eliminate error factors and ensure accurate measurement results.



Factor Analysis Chart for Measurement Errors

1-2-1 Precautions on the Measuring Room

Temperature / Humidity	\rightarrow	Try to maintain constant room temperature as much as possible to prevent dew condensation and unstable indications due to fluctuations in temperature.
	\rightarrow	Low relative humidity tends to induce static electricity, causing measurement error. (Relative humidity of about 60% is considered ideal.)
Vibration/ Shaking	\rightarrow	The measuring room should preferably be located on the ground floor or in the basement. Higher floors are more susceptible to heavy vibration and shaking, which make such locations less suitable for measurement. A room facing a railway or road with heavy traffic should also be avoided as much as practicable.
Drafts	\rightarrow	Avoid choosing a location subject to a direct draft of airflow from an air-conditioning unit or exposed to direct sunlight, which may cause unstable reading due to abrupt fluctuations in temperature.
		Also avoid a room subject to a heavy flow of people, since fluctuations in drafts and temperature are likely to occur in such a location.
Gravity	\rightarrow	The gravity acting on a sample varies depending on the latitude or height of the location where measurement is being conducted. For this reason, the same sample may show different weight indications from one place to another.
		Therefore, make it a rule to calibrate the balance every time it is relocated.
Electromagnetic Waves	→	When the balance is located near an object that generates intense electromagnetic waves, it may be hindered from showing accurate weight due to the effects of such waves. Therefore, avoid placing the balance in such a location.

1-2-2 Precautions on the Measuring Bench

Vibration/ Shaking	→ →	If the balance is subjected to vibration during measurement, its indications will become unstable, thus preventing accurate measurement from being conducted. To avoid this situation, select a solid measuring bench that is less susceptible to vibration. (A bench in a vibration-proof structure or one made of concrete or stonework will be suitable.) Moreover, do not conduct measurement with a soft cloth or paper placed under the balance, since the balance may be rocked out of its precise level positioning. Place the measuring bench in a location free from vibration as much as possible. It is a good idea to install the measuring bench in a corner of the measuring room, where less vibration is likely to occur than in the center of the room.
Magnetism/ Static Electricity	\rightarrow	Avoid operating the balance on a bench that is susceptible to the effects of magnetism or static electricity.

1-2-3 Precautions on the Samples

Static Electricity	\rightarrow	Generally speaking, objects made of synthetic resin and glass has high electric insulating properties and, therefore, are apt to be electrically charged. Measuring a charged sample as is may cause unstable indications, with resultant poor reproducibility of the results. With this in mind, be sure to discharge charged samples before measurement.
Magnetism	\rightarrow	A sample affected by magnetism indicates different weight values depending on where it is located on the measuring pan, along with resultant poor reproducibility of the results.
		When a magnetized sample must be measured, first demagnetize it or place an appropriate pedestal on the measuring pan to adequately separate the mechanism part of the balance from the magnetized sample for avoiding the effects of magnetism.
Absorption/ Evaporation of Moisture	\rightarrow	Measuring a sample with moisture absorbed or evaporated (volatized) continuously increases or decreases the values indicated. In such case, measure the sample in a container with a small opening and sealed airtight with a cap.
Sample Temperature	→	A difference in temperature between a sample and the interior of a windshield may cause convection to occur inside the windshield, resulting in erroneous measurement. Therefore, measure a very hot or cold sample only after allowing time for its temperature to acclimatize to room temperature. Moreover, to prevent convection inside the windshield, allow time for the interior of the windshield to acclimatize to room temperature.
	\rightarrow	The body heat of a person conducting measurement can also affect measurement results. Avoid holding the sample with bare hands, and use long tweezers or a similar tool instead. Also refrain from putting your hands inside the windshield while measurement is in progress.


1-2-4 Precautions on the Main Unit of the Balance


Precautions on Use	\rightarrow	A transparent dust cover, supplied for some models, may be statically charged under low humidity conditions, which may cause unstable readinig. In such case, wipe the dust cover with a damp cloth or use a commercial antistatic agent. Otherwise, simply operate the balance with the dust cover removed.
	\rightarrow	For more stable measurement, it is recommended to have 30 minutes warm up time after power-up, and apply a load equivalent to the weighing capacity several times before conducting actual measurement operation.
Calibration	\rightarrow	Periodically calibrate the balance with an internal or external calibration weight to ensure accurate measurement at all times.
	\rightarrow	For more precise calibration, use an external calibration weight that approximates the weighing capacity. Moreover, calibrate the balance only after enough warm up time and loading near capacity weight.
	\rightarrow	Calibration is also required in the following cases:
		When operating the balance for the first time,
		When not using the balance for a long time,
		When relocating the balance, or
		When there is wide fluctuation in temperature, humidity or atmospheric
		pressure.
Maintenance	→	When the measuring pan or pan base is contaminated with powder or liquid, erroneous weight values may result or indications may remain unstable. Therefore, be sure to frequently clean the balance. When cleaning the balance, be very careful not to allow dirt or liquid to penetrate inside (the mechanism part).


2. Names of Component Parts

2.1 Main Unit

Capacity(g)	Pan type
220~620	Round
820~12K	Square







2.2 LCD Indicators and Operating Keys

2.2.1 Symbols Displayed




Display	Description
g	Grams
→0←	Zero point
0	Indication of stable balance (If the light is off, the balance is unstable.)
*	Balance powered up (Lights up when the power is turned off) or data transmitted
Pcs	Counting mode
%	percentages mode
◀	Indication of judgement result (HI/OK/LO) when the limit function is active.
M	Display of set values from memory (If a value is flashing, it is being saved.)
CAL	Stays on and flashes while span adjustment is in progress.
	Auxiliary scale interval (Lights up only when the auxiliary scale interval is displayed.)
Omhuhuhu F	Bar graph
ජ lක්ද ▶	[ct] (ct) carat [az] (oz) ounce [b] (lb) pound [az t] (ozt) troy ounce [dいた] (dwt) pennyweight [► (Upper right)] grain
4	It stays on [L] when operated by rechargeable battery or dry cell battery. It flashes [L] when the battery capacity becomes low. (Refer to page 38 or 39.) It does not show when powered by AC adaptor.


2.2.2 Names and Functions of Operating Keys

Ор	erating Key	Function		
ON/OFF	On/off key	Key to turn on/off the unit power		
Р	Memory key	[Brief press] initiates print or output. [Brief press] saves the settings of the number of pieces or the limit value when using the limit function.		
S	Set key	[Brief press] [Continuous press]	starts setting the number of pieces or percentages (%). starts setting the limit value when using the limit function.	
F	Function key	[Brief press] [Brief press] [Brief press] [Continuous press] [Longer continuous press]	toggle-switches the units to be displayed in succession (g, Pcs, etc.). moves the flashing digit in the setup of a limit value when using the value input method. selects an item when setting the function. invokes various functions. invokes span adjustment.	
→0←	Zero key	[Brief press] [Brief press] [Brief press]	resets the indication to zero when using zero-point setup. selects a value with the value input method when using the limit function. selects a function when operating the balance in the function mode.	


3. Basic Operations

3.1 Installation







3.2 Operation Check



3.3 Operation for Zero Adjustment




☆ Weighing only the weight of an added sample




★ Key Points of the Procedure **★**

The following applies equally to all the measurement modes for weight measurement, counting, and percentages.

- 1. After the balance is switched off, there is still enough current to display [*]. This indicates that the AC adapter is connected to an electrical outlet, but that the balance is turned off. When the balance is switched on again, [*] will disappear.
 - ※If the balance is running on batteries and the unit is switched off, the display does not display [★].
- 2. The bar graph shows the current load status with respect to the capacity of the balance. The nearer the [F] mark draws, the smaller the measurable weight becomes.
 - ※Even when the display currently indicates zero with the weight subtracted, the weight corresponding to the gross value is indicated on the bar.



3. When the balance remains stable, the stability indicator [O] remains on. If the balance becomes unstable, the stability indicator [O] will disappear. When a displayed value flickers or the stability mark flashes on and off, it is likely that the balance is being affected by wind or other vibrations. Use the windshield or vibration dampers to protect against such adverse effects.





4. When the read-out indicator is reset to zero, the balance indicates zero this way: $[\rightarrow 0 \leftarrow]$.




* If the indication deviates from the true zero point by 1/4 of a graduation or less, [→ 0 ←] disappears.



- * If the tare is subtracted, the balance indicates zero.
- 5. Only weight fraction that was canceled, the measurable range is reduced. Measurable Range = Capacity container weight.
- 6. If [o-Err] appears when a sample is loaded, the measurable range has been exceeded.
- 7. In counting mode, if no sample is stored in memory the indicator will not change, even when the measurement pan is pressed.
- 8. The measurement mode that is activated when the balance is switched on will be the one that was active when last switched off. For example, if the balance was switched off in counting mode, this counting mode will be reactivated the next time the balance is switched on.

4. Functions

4.1 Setup and Checking of Functions



4.2 Description of Functions

	Item	Set V	alue alue	Description	
Rar or	Bar graph display 1. b.G0		Disable		
Bai grapii dispiay		1. b.G.	☆ 1	Enable	
Limi	t function	2.SEL		Disable	
	t lanction	2.0LL	1	Enable	
i i i	Judgement	21.Co.	☆ 1	unstable)	
en lin ated	condition	21.00.	2	Judge only when the balance judge if the balance is unstab	
ly wh activ	ludgamant		0	Ranges beyond +5 graduatio graduation or below, including	
on si r	Judgement range	22.Li		not judged.)	
Displayed only when limit function is activated	runge		☆ 1	The entire range is judged (the including the negative, is judged)	
lisp ft	Number of		1	One-point setup (judges betw	
	points for judgement	23.Pi	☆2	Upper-limit and lower-limit va among HI, OK and LO).	lues are set up (judges
			0	Disable (balance operates continuously)	This function is available only when
Auto power-off		4. A.P.	☆1	Enable (balance powers off in approximately three	the balance is battery-operated.
				minutes)	
			0	Measurement by consecutive weighings.	
			1		
Respo	onse speed	5. rE.		Fast	
. 100pon.00 opoou			☆3	Claur	
			5	Slow	
				Disable input/output	
In	terface	7. I.F.		Six-digit numeric format	
"'			2	Seven-digit numeric format	
				[g]	
1				ct	
Setup of units of measurement to be displayed Register selected measuring units with Function key.			15	[az] (oz)	
		81.S.u.		[/b] (lb)	
				[az t] (ozt)	
		85.S.u.	18	[dvyt] (dwt)	
			19* ¹	[Lower right] (grain)	
				[Pcs]	
				[%] Unit not set	
		a dafault faat	· ·	OTHE HOL SCE	

Items mrked ☆ are the default factory settings.

\$\price 1 \sim \price 5: default factory settings [81.S.u.] \sigma[85.S.u.]

☆6: AJ-NTDB Type only

※1 For 220g∼6200g Capacity model

4.3 Interface Section

Displayed when [7. I.F.] is set to [1] or [2]


Item	Set V	alue	Description	
	71. o.c.	0 2	Stop output Output continuous if stable (stop output if unstable) Outputs once if stable. Outputs if the balance is stable when a sample is loaded after the preceding sample	
Output Control		4	has been removed and the balance indicated zero, or less.	
		5	Outputs once if stable, and stops output when unstable. Even if the sample is not replaced, the balance is output once when it stabilizes next time (including the zero indication).	
		☆ 7	Pressing Memory key causes the balance to output once when stable.	
			1200 bps	
Baud Rate	72. b.L.	2	2400 bps	
Dadd Nate		3	4800 bps	
		4	9600 bps	
Parity	73. PA.	±0 1 2	None Odd (7-digit numeric format) is specified.	

[☆] denotes a factory-setting

5. Switching Function for Units of Measurement

5.1 Switching Units of Measurement


Pressing the Function key allows the user to switch the unit of measurement to [g], [ct] and so on.




5.2 Setup of Units of Measurement

When values [81.S.u.] to [85.S.u.] are entered prior to use, the desired unit of measurement to be displayed can be chosen simply by pressing the Function key. For more information on the units of measurement that can be set here, please refer to "4.2 Description of Functions" on page 17.

Example:To change the default factory settings to pound units, use [82.S.u.] .



Example: To change the default factory settings to pound units use [82.S.u.]. (cont.)




★ Key Points of the Procedure ★

- 1. When set values are entered in the function items [81.S.u.] to [85.S.u.] prior to use, the desired unit of measurement to be displayed can be selected simply pressing the Function key. For more information on the units of measurement that can be set, please refer to "4.2 Description of Functions," on page 17.
- 2. The units are displayed in the same sequence as the settings made from [81.S.u.] to [85.S.u.].
- 3. If [00] is set, no unit of measurement will be displayed, even when units of measurement are set in subsequent items.
- 4. [00] cannot be set in [81.S.u.].
- 5. If the same unit of measurement is set multiple times, the second time (and all subsequent times) the unit(s) occurs, it will be ignored when the display switches.

6. Counting Pieces


To implement piece-counting, the specified samples are loaded on the balance, and their average unit weight (hereinafter, simply the "unit weight") is entered and saved. The procedure for saving unit weights is called sampling.


The counting procedure consists of loading articles that have already been sampled on to the balance. The number of pieces is then calculated by dividing the total weight of the loaded articles by the unit weight saved in memory. Piece counting cannot be implemented unless sampling has already taken place.



If samples to be counted deviate widely in weight, or a higher measure of accuracy is desired, it is recommended that users use the "Raising the Counting Accuracy" method. This procedure results in greater precision by increasing the number of samples used in the sampling operation.

6.1 Sampling





☆ Key Points of the Procedure **☆**

- 1. While the samples are being saved, the value indication disappears and only [M] flashes to indicate that memory saving is underway. If the balance is affected by wind or other vibrations during this process, the saving time may be prolonged.
- 2. If [L-Err] appears, it indicates one of the following states:
 - (1) The weight of one sample (measurable unit weight) is insufficient. For the range of unit weights that can be measured and saved, please refer to "13. Specifications," on page 41.
 - (2) In the sampling of Operation Step 3, press the Set key with the samples loaded on the balance.
 - If [L-Err] appears, the sampling is interrupted and the data in progress is not saved.

 If [L-Err] appears, the sampling is interrupted and the data in progress is not saved.

 If [L-Err] appears, the sampling is interrupted and the data in progress is not saved.

 If [L-Err] appears, the sampling is interrupted and the data in progress is not saved.

 If [L-Err] appears, the sampling is interrupted and the data in progress is not saved.

 If [L-Err] appears, the sampling is interrupted and the data in progress is not saved.

 If [L-Err] appears, the sampling is interrupted and the data in progress is not saved.

 If [L-Err] appears, the sampling is interrupted and the data in progress is not saved.

 If [L-Err] appears, the sampling is interrupted and the data in progress is not saved.

 If [L-Err] appears, the sampling is interrupted and the data in progress is not saved.

 If [L-Err] appears, the sampling is interrupted and the data in progress is not saved.

 If [L-Err] appears, the sampling is interrupted and the data in progress is not saved.

 If [L-Err] appears, the sampling is interrupted and the data in progress is not saved.

 If [L-Err] appears, the sampling is interrupted and the data in progress is not saved.

 If [L-Err] appears, the sampling is interrupted and the data in progress is not saved.

 If [L-Err] appears, the sampling is interrupted and the data in the data
- 3. The operation for increasing counting accuracy is referred to as the Memory Update Method. This procedure updates the memory with a unit weight that represents a more precise average by gradually increasing the sampling number.

This operation improves counting accuracy and is recommended for the following cases;

- (1) When the samples to be counted deviate widely in weight or the number of samples displayed deviates.
- (2) When greater accuracy is desired.
- 4. If [Add] appears in Memory Update Method, it indicates that a counting error is likely due to the small number of the samples loaded on the balance. [◀] will light up at the judgment indication "LO." As the memory update continues, counting accuracy improves and the above indication disappears.
- 5. If you change the sampling number, subsequent sampling will start from the new sampling number.


6.2 Increasing the Counting Accuracy (Memory Update Method)

*This procedure is the same as the sampling procedure described on the previous page up, to the point at which the sampling number is changed.

1	Loading samples	Load the number of samples displayed.
	Pos M D C IB 'I	Count the samples precisely and load them on to the center of the measurement pan.
2	Saving the samples	Press the Set key.
	10 pieces saved	The unit weight of the samples is saved, and the display changes to a flashing value. This flashing value denotes that the Memory Update Method is currently active.
3	Adding samples	Add approximately an equal number of samples as the number currently
	Pcs Pcs	displayed. Add them gradually, in groups of approximately the same number, until the number of samples is approximately double. The additional samples need not be counted.
4	Saving the samples 20 pieces saved	Press the Set key.
	Pcs Pcs Pcs	After the unit weight of the samples has been saved, the display begins to flash, indicating that the Memory Update Method is still running.
5	Repeating the addition and saving of samples	Repeat steps 3 and 4. The eventual total number of samples to be saved
		should be approximately 1/5 to 1/2 of the number of samples to be measured.
6	Terminating the sampling 125 pieces saved	Press the Memory key.
	Pcs 125	The balance saves the unit weight and returns you to measurement mode.

7. Measuring Percentage (AJ-NT Type only)

The percentage measurement function operates by weighing an actual sample, selected as the reference, and saving its weight as the reference value and indexing it as 100%. When a measurement sample loaded on the balance is lighter or heavier than the reference, its weight is indicated as a percentage (%) value relative to the reference weight.



★ Key Points of the Procedure **★**

- While samples are being saved, the value indication disappears temporarily, and only the [M] mark flashes. If the balance is affected by wind or other vibrations during this process, the saving time may be prolonged.
- 2. If [L-Err] appears briefly, it indicates one of the following states:
 - (1) The weight of the reference sample is insufficient. For the limit weight that can be saved (% limit weight), please refer to "13. Specifications," on page 41.
 - (2) While setting up the reference value in Step 2, the Set key has been pressed while the samples were loaded on the balance.
 - ※If [L-Err] appears, sampling has been interrupted and the sample value being processed will
 not be saved.
- 3. The minimum intervals between percentages in the unit switch from 1%, to 0.1%, to 0.01%, depending on the reference weight from the sampling.

8. Limit Function

The limit function judges measurements according to a limit value saved in the balance.

The function shows the judgement result by displaying the [◀] mark as either HI (excessive), OK (appropriate), or LO (insufficient). This function is very useful when discriminating between conforming and nonconforming articles. It is also useful when measuring a given constant quantity consecutively, in conjunction with a range of reference weights defined by upper- and lower-limit values.

This function can be used in weight mode, counting mode, or percentage mode.

Limit value input methods

Either of the following two methods can be used in the different modes:


- (1) Actual quantity setup method An actual sample is loaded on the balance and its weight saved as the limit value.
- (2) Numeric value setup method The limit value is entered with a key stroke.
- *The limit values entered are held in memory, even when the balance is powered down.
- *The respective limit values for weight mode, counting mode, and percentage mode are set up independently.

Indication of judgement result


The [◀] mark lights up as either HI, OK, or LO on the left side of the display, indicating the result of judgement.

Judgement Results	Upper/lower-limit setting	One-point setting
HI (excessive)	Upper-limit value < measurement value	No indication
OK (appropriate)	Upper-limit value ≥ measurement value ≥ lower-limit value	Limit value ≤ measurement value
LO (insufficient)	Lower-limit value > Measurement value	Limit value > Measurement value


8.1 Limit Function Setup




8.1 Limit Function Setup (cont.)




8.2 Setup of Limit Values by Actual Quantity Loads



8.3 Setting up Limit Values by Inputting Values




8.3 Setting up Limit Values by Inputting Values (cont.)



★ Key Points of the Procedure ★

1. The limit values you have set can be checked each time you press the Set key.

The balance displays the lower-limit value after showing [L. SEt], and the upper-limit value after showing [H. SEt].




- 2. If you make a mistake, press the Function key during the setup of actual quantities or the Set key during the setup of values.
- 3. If you press the Memory key while a value is flashing, an actual quantity will be set based on the weight currently loaded on the balance. Pressing the Zero key at this time displays the value input screen.
- 4. If the [◀] mark lights up for all three judgement indicators, HI, OK, and LO, the lower-limit value set exceeds the upper-limit value. Check the values, since mistakes can occur with entries, as in cases when the upper-limit value is specified with a negative sign.
- 5. When the [M] mark is flashing on the value input screen, the sign on the left end can be changed. Press the Zero key to switch between the positive and negative signs.

9. Input/output functions

9.1 Terminal Numbers and Functions

Terminal Number	Signal	Input/output	Function & remarks
1	EXT.ZERO	Input	External Zero adjustment*
2	DTR	Output	HIGH (when balance is powered-up)
3	RXD	Input	Receiving data
4	4 TXD Outpu		Transmitting data
5	GND	_	Signal ground



RS232C connector (DIN 5-pin female): Rear


Caution:

Before plugging in the connectors, unplug the AC adapter.


<sup>XZero adjustment is possible by connecting an external zero adjustment input and a signal ground,
through contacts or a transistor switch. When following this procedure, secure a connection time of
at least 400 milliseconds. (When the switch is off, the voltage maximum is 15 V; when the switch is
on, the sink current is 20 mA or less.)</sup>

9.2 Connection between Balances and Personal Computers

■■■ Sample connection with an IBM-PC/AT compatible ■■■



■■■ Sample connection with PC9801 ■■■



9.3 Interface Specifications

(1) Transmission system Serial transmission with start-stop synchronization

(2) Transmission rates 1200/2400/4800/9600 bps.

(3) Transmission codes ASCII codes (8-bit)


(4) Signal levels Compliant with EIA RS-232C

HIGH level (Data logic 0) +5 to +15 V LOW level (Data logic 1) -5 to -15 V

(5) One-character bit configuration Start bit: 1 bit

Data bit: 8 bits
Parity bit: 0/1 bits
Stop bit: 2 bits

(6) Parity bit: none/odd/even



9.4 Output Data

By changing the function settings on the main unit of the balance, users can select either of the following formats: (See "4.2 Description of Functions," on page 17.)

9.4.1 Data Format

(1) Six-digit numeric format

Composed of 14 characters, including the terminators (CR = 0DH, LF = 0AH).

													14
P1	D1	D2	D3	D4	D5	D6	D7	U1	U2	S1	S2	CR	LF

(2) Seven-digit numeric format

Composed of 15 characters, including the terminators (CR = 0DH, LF = 0AH). A parity bit can also be appended.

1														
P1	D1	D2	D3	D4	D5	D6	D7	D8	U1	U2	S1	S2	CR	LF

(3) Six-digit numeric format for model provided with an auxiliary scale interval Composed of 15 characters, including the terminators (CR=0DH, LF=0AH), with "/" added to the

Composed of 15 characters, including the terminators (CR=0DH, LF=0AH), with "/" added to the left of the auxiliary-scale-interval place.

			_		_	_		-	-	_			_		15
ĺ	P1	D1	D2	D3	D4	D5	D6	D7	D8	U1	U2	S1	S2	CR	LF

(4) Seven-digit numeric format for model provided with an auxiliary scale interval Composed of 16 characters, including the terminators (CR=0DH, LF=0AH), with "/" added to the

left of the auxiliary-scale-interval place.

1		_		_	_		-	-	_			_		-	_
P1	D1	D2	D3	D4	D5	D6	D7	D8	D9	U1	U2	S1	S2	CR	LF

9.4.2 Polarities (P1: one character)

P1	Code	Description
+	2BH	When data is zero or positive
-	2DH	When data is negative
(SP)	20H	When data is zero or positive

9.4.3 Numeric data

Six-digit numeric format: (D1–D7: seven characters)
Seven-digit numeric format: (D1–D8: eight characters)

Six-digit numeric format for model provided with an auxiliary scale interval:

(8 characters, from D1 to D8)

Seven-digit numeric format for model provided with an auxiliary scale interval:

(9 characters, from D1 to D9)

D1-D7 (D8)	Code	Description
0–9	30H-39H	Numerical value 0–9
		Decimal point (floating position)
•	2EH	When the data is an integer, it may be omitted and replaced with a blank space (SP) in the lowest-order place.
(SP)	20H	Space: zero of leading portion of value (leading zero suppress)
1	2FH	Delimiter to be inserted to the left of the auxiliary-scale-interval place

9.4.4 Units (U1, U2: two characters)

* All the codes are ASCII codes.

U1	U2	Code		Code Meaning		Balance indicators
(SP)	G	20H	47H	gram	g	
С	Т	43H	54H	carat	ct	
0	Z	4FH	5AH	ounce	07	
L	В	4CH	42H	pound	Ъ	
0	T	4FH	54H	troy ounce	oz t	
D	W	44H	57H	pennyweight	dirit	
G	R	47H	52H	grain	(lower right)	
Р	С	50H	43H	pieces	Pcs	
(SP)	%	20H	25H	percentage	%	

9.4.5 Result of judgment when operating the balance with the limit function (S1: one character)

S1	Code	Description			
L	4CH	LO (LOW)			
G	47H	OK (GOOD)			
Н	48H	HI (HIGH)			
(SP)	20H	No limit value specified			

9.4.6 Status (S2: one character)

S2	Code	Description		
S	53H Data stable			
U	55H	Data unstable		
Е	45H	Data error (data other than S2 is invalid.)		
_	45П	[o-Err], [u-Err]		
(SP)	20H	No status specified		

9.5 Input Commands

Users can control the balance remotely by transmitting commands from an external device. Two types of control commands are available:

- (1) Instruction for zero adjustment
- (2) Setup of output control

9.5.1 Command Transmission Method

- (1) A command is transmitted to the balance from an external device. Since the data flow (transmission and reception) is stored by a full-duplex system, commands can be transmitted regardless of their data-transmission timing.
- (2) When the balance has executed the received command, it activates a normal end response or transmits the requested data, via the transmitting command. If the balance was unable to execute the command or received an erroneous command, it transmits an error end response. If the balance is working properly, it usually returns a response within a second after it receives the transmitted command. If the balance receives a transmission while it is conducting a procedure (such as the setup of a function or a span adjustment), it will transmit a response when the procedure finishes.
- (3) When transmitting more than one command to the balance from a remote device, wait until you have received a confirmation on the first transmission before transmitting the next.

9.5.2 Command format

(1) Command format

Composed of four characters (ASCII), including the terminators (CR=0DH, LF = 0AH)

1	2	3	4
C1	C2	CR	LF

(2) Instruction for zero adjustment

C1	C2	Code		Description	Value	Response
Т	(SP)	54H	20H	Instruction for zero adjustment	None	A00: Normal end E01: Zero adjustment cannot be executed due to an error in the weight value.

(3) Setup of output control

C1	C2	Co	de	Description			
0	0	4FH	30H	Stop output			
0	2	4FH	32H	Output continuous if stable (stop output if unstable)			
0	4	4FH	34H	Outputs once if stable. Outputs if the balance is stable when a sample is loaded after the preceding sample has been removed and the balance indicated zero, or less.			
0	5	4FH	35H	Outputs once if stable, and stops output when unstable. Even if the sample is not replaced, the balance is output once when it stabilizes next time (including the zero indication).			
0	7	4FH	37H	Pressing Memory key causes the balance to output once when stable.			
0	9	4FH	39H	Output once after stabilization.			

^{*}The output controls executed with commands [O0] - [O7] work the same as the output controls executed through function setup on the main unit of the balance.

The commands [O9] are data request commands issued to the balance.

9.5.3 Response Output

(1) Response output format

Composed of five characters, including the terminators (CR = 0DH; LF = 0AH)

1	2	3	4	5
A1	A2	А3	CR	LF

(2) Types of response outputs

A1	A2	A3	Code		Code Description	
Α	0	0	41H	30H	30H	Normal end
E	0	1	45H	30H	31H	Command error (Abnormal command received; other errors)

^{*}Once any command from [O0] to [O9] is executed, the balance runs that function until another command is entered. However, if the balance is switched off and on again, the output control is reset to the initial function (function set value).

10. Operating the Balance with the Battery

This function can be used only when the balance is battery-operated.

10.1 Specifications

Built-in nickel-cadmium battery

Charging time: Approximately 12 hours

Drive time: Approximately 24 continuous hoursNumber of charge/discharge cycles: 300 or more

10.2 Charging Method

*While the balance is battery-operated, [1] stays on. The indicator displays [Lo-bAt] and flashes [1] (charging required) when battery capacity decreases. If the balance flashes [1], charge the battery by following these steps:

- (1) Connect the dedicated AC adaptor to the balance.
- (2) Turn the balance off.
- (3) Charging takes approximately 12 hours, with power switched off. Charging the battery longer than 12 hours decreases battery life.

10.3 User Precautions

- Once charging is complete, use the balance without the AC adaptor to avoid over-charging.
 This can occur since the balance continues to charge the battery with a weak current when the power is switched on. Overcharging will also decrease battery life.
- 2. When the balance is used for the first time after purchase, the operating time may be shorter than when using a fully charged battery. This is due to natural discharge of the battery. Although the balance can be used while [[] is flashing, it should be recharged as soon as possible.
- When the battery displays no indication, or an indication disappears quickly after the balance is switched on, battery capacity is low. In these cases, either charge the battery immediately or plug in the AC adaptor.
- 4. Charging the battery while [is displayed reduces battery life.
- 5. Operable hour will be shorten when [7. I.F. 1/2] is selected, because some power is consumed for interface even with no output.



To operate the balance safely, observe the following (failure to do so could result in malfunctions, breakage, burst batteries, or fire):

- 1. Do not disassemble or modify the battery. Do not reverse the balance connection or short-circuit the positive and negative polarities of the balance.
- 2. Use only the supplied AC adaptor.
- 3. Do not incinerate used batteries. Dispose as hazardous material only.

11. Operating the Balance with the Dry Cell Battery (DBNT)

This function can be used only when the balance is dry-cell-battery-operated.

11.1 Specifications

• Cell type for use: 9 Volt (006P) (alkali type recommended)

• Drive time: Approximately 20 continuous hours

**depend on model, storage and operation condition

11.2 User Precautions

- 1. While the balance is battery-operated, [stays on. The indicator displays [Lo-bAt] and flashes [lashes [
- 2. The balance can be operated with AC adaptor, while the dry cell battery is installed. ([does not show in this case.)
- 3. Operable hour will be shorten when [7. I.F. 1/2] is selected, because some power is consumed for interface even with no output.



To operate the balance safely, observe the following (failure to do so could result in malfunctions, breakage, burst batteries, or fire):

- Do not disassemble or modify the battery. Do not reverse the balance connection or short-circuit the positive and negative polarities of the balance.
- 2. Use only the supplied AC adaptor.
- 3. Do not put batteries into fire.

12. Troubleshooting

X The numbers in () indicate reference pages

Symptom	Cause	Possible remediation
There is no indication on the display.	The AC adapter is not connected.	→ Check that the AC adapter is connected (12).
The display is unstable. [M] remains flashing without changing.	 The balance is subject to air currents or vibration. The balance is situated on an unstable surface. An object is contacting the sample being measured, the measuring pan, or the container. 	→ Check Precautions on the Use (2).
Weight indication contains an error.	 An error was made in the zero adjustment procedure. The adjusters remain lifted, resulting in an incorrect level. The indication values are inconsistent after long hours of use, or because the balance has been moved to a new location. 	 → Review the zero adjustment (14). → Check the level (12).
The limit function does not work.	 The limit function is not selected. The limit value has been erroneously entered. 	→ Check the operation of the limit function (26 on).
[Hdd] appears ([◀] and a value flash at [LO].)	Likely to produce errors in the counting mode because the sample weight is insufficient.	→ Execute the Memory Update Method (23).
[o-Err] appears before the capacity is reached.	 Gross weight exceeded the capacity of the balance (weight range = container + weight of sample). A section of the mechanism is damaged. 	 → Check the total weight. → Execute zero adjustment again. → Contact our local dealer.
[u-Err] is displayed.	 A foreign object is caught between the measuring pan (pan base) and the balance. A section of the mechanism is damaged. 	→ Remove the measurement pan and examine the surface beneath it.
[b-Err] is displayed. [d-Err] is displayed.	 The balance is exposed to static electricity or noise. The electrical system of the balance is malfunctioning. 	→ Contact our local dealer.
During battery installation: The indication disappears. [Lo-bAt] is display. [Label of the second of	 The automatic power-off function was activated. The battery capacity is low.(AJ-NT) The dry cel battery capacity is low.(AJ-DBNT) 	→ Switch on the power again. Deactivate the Automatic power-off function, if necessary (17). → Recharge the battery (38).(AJ-NT) → Replace the dry cell battery(39).(AJ-DBNT) → Operate the balance with the AC adapter.

13. Specifications

13.1 Basic Specifications

	AJ-	AJ-	AJ-	AJ-	AJ-	AJ-		
Model	220NT	320NT	420NT	620NT	820NT	1200NT		
	/DBNT	/DBNT	/DBNT	/DBNT	/DBNT	/DBNT		
Max	220g	320g	420g	620g	820g	1200g		
Min	0.02g	0.02g	0.02g	0.1g	1g	0.5g		
е	0.01g	0.01g	0.01g	0.01g	0.01g	0.1g		
d	0.001g	0.001g	0.001g	0.001g	-	0.01g		
Accuracy class		class II		clas	ss I	class II		
Measurable unit weight in counting mode	0.03g	0.03g	0.03g	0.03g	0.03g	0.3g		
Minimum weight in percentage mode	0.1g	0.1g	0.1g	0.1g	1g	1g		
Weight measuring method		Tuning fork vibration method						
Pan Size		φ118	3 mm		170mm x	k 140mm		
Output			Compliant w	vith RS232C	;			
Windshield		Provided Not provided						
Option		В	attery drive	(Only AJ-N	Γ)			

Model	AJ- 2200NT /DBNT	AJ- 3200NT /DBNT	AJ- 4200NT /DBNT	AJ- 6200NT /DBNT	AJ- 8200NT /DBNT	AJ- 12KNT /DBNT		
Max	2200g	3200g	4200g	6200g	8200g	12000g		
Min	0.5g	0.5g	0.5g	1g	5g	5g		
е	0.1g	0.1g	0.1g	0.1g	1g	1g		
d	0.01g	0.01g	0.01g	0.01g	0.1g	0.1g		
Accuracy class		class II		class I	clas	ss II		
Measurable unit weight in counting mode	0.3g	0.3g	0.3g	0.3g	3g	3g		
Minimum weight in percentage mode	1g	1g	1g	1g	10g	10g		
Weight measuring method		Tuning fork vibration method						
Pan Size		180mm x 160mm						
Output	Compliant with RS232C							
Windshield		Not provided						
Option		В	attery drive	(Only AJ-N	Γ)			

13.2 Common Specifications

(1)	Zero adjustment range	. Total capacity
(2)	Liquid-crystal display (LCD)	Seven segments (two segments in leading part) , Maximum digits indication: seven digits, Segment height: 16.5 mm.
(3)	Overload indication	[o-Err] is displayed if weight capacity + 9 intervals are exceeded.
(4)	Compatible printer	. CSP-160
(5)	Operating temperature and humidity ranges.	. 10°C to 30°C, 80%RH or less for class II 12.5°C to 27.5°C, 80%RH or less for class I
(6)	AC adapter	Dedicated AC adapter: 120 V AC - 9 V DC
(7)	Lower limit of battery voltage	. 6V

13.3 Capacities and Minimum Indications for Different Indication Units

Unit of measurement displayed	AJ-220NT /DBNT	AJ-320NT /DBNT	AJ-420NT /DBNT	AJ-620NT /DBNT	AJ-820NT /DBNT	AJ- 1200NT /DBNT
	220	320	420	620	820	1200
g	0.01	0.01	0.01	0.01	0.01	0.1
	0.001	0.001	0.001	0.001	-	0.01
	1100	1600	2100	3100	4100	6000
C亡 (ct)	0.1	0.1	0.1	0.05	0.05	1
	0.01	0.01	0.01	-	-	0.1
	7.7	11	14	21	28	42
OZ (OZ)	0.001	0.001	0.001	0.001	0.0005	0.005
	0.0001	0.0001	0.0001	0.0001	-	-
	0.48	0.7	0.92	1.3	1.8	2.6
b (lb)	0.00005	0.0001	0.0001	0.0001	0.00005	0.0005
	-	0.00001	0.00001	0.00001	0.01 - 4100 0.05 - 28 0.0005 - 1.8 0.00005 - 26 0.0005 - 520 0.01 - 12000	-
	7	10	13	19	26	38
ロZ て(ozt)	0.001	0.001	0.001	0.001	0.0005	0.005
	0.0001	0.0001	0.0001	0.0001	-	-
	140	200	270		520	770
dvyt (dwt)	0.01	0.01	0.01	0.01	0.01	0.1
	0.001	0.001	0.001	0.001		0.01
	3300	4900	6400	9500	12000	18000
(grain)	0.2	0.2	1	1	0.2	2
	-	-	0.1	0.1	-	-

Model	AJ-	AJ-	AJ-	AJ-	AJ-	AJ-
Unit of	2200NT	3200NT	4200NT	6200NT	8200NT	12KNT
measurement displayed	/DBNT	/DBNT	/DBNT	/DBNT	/DBNT	/DBNT
	2200	3200	4200	6200	8200	12000
g	0.1	0.1	0.1	0.1	1	1
	0.01	0.01	0.01	0.01	0.1	0.1
	11000	16000	21000	31000	41000	60000
に (ct)	1	1	1	0.5	5	5
	0.1	0.1	0.1	-	-	-
	77	110	140	210	280	420
OZ (OZ)	0.01	0.01	0.01	0.01	0.05	0.05
	0.001	0.001	0.001	0.001	-	-
	4.8	7	9.2	13	18	26
b (lb)	0.0005	0.001	0.001	0.001	0.005	0.005
	-	0.0001	0.0001	0.0001	-	-
	70	100	130	190	260	380
ロ z	0.01	0.01	0.01	0.01	0.05	0.05
	0.001	0.001	0.001	0.001	-	-
	1400	2000	2700	3900	5200	7700
dレッセ (dwt)	0.1	0.1	0.1	0.1	1	1
	0.01	0.01	0.01	0.01	0.1	0.1
	33000	49000	64000	95000		
(grain)	2	2	10	10		
	-	-	1	1		

Reading the Table

Top line: Capacity

Middle line: Verification scale interval Bottom line: Auxiliary scale interval

14. Conversion Table of Units

unit	gram	carat	ounce	pound	troy ounce	penny weight	grain
1g	1	5	0.03527	0.00220	0.03215	0.64301	15.43236
1ct	0.2	1	0.00705	0.00044	0.00643	0.12860	3.08647
1oz	28.34952	141.74762	1	0.06250	0.91146	18.22917	437.5
1lb	453.59237	2267.96185	16	1	14.58333	291.66667	7000
1ozt	31.10348	155.51738	1.09714	0.06857	1	20	480
1dwt	1.55517	7.77587	0.05486	0.00343	0.05	1	24
1GN	0.06480	0.32399	0.00229	0.00014	0.00208	0.04167	1