

This document hosted by

***OldWillKnottScales***

~ ~ CLICK HERE ~ ~

to visit us the next  
time you need a scale!

# **My Weigh Uber Alum User Manual**

# über<sup>TM</sup> alum

Brushed Aluminum Kitchen Scale

Balance de cuisine en Aluminium Brossé

Abgebürstetes Aluminium-Küchenwaage

**5000g x 1g Capacity**

## Specifications:

- 5000g x 1g Capacity
- Reads in 3 Standard Modes
- Hold & Tare Feature
- Red LCD Digital Display
- Brushed Aluminum Finish
- Auto/Manual OFF
- Power: 4 x 1.5V AAA batteries
- Touch-style Switch

<b>Capacity</b>	5000g / 11.0231lb / 17.637oz
<b>Readability</b>	1g / 0.0021b / 0.05oz
<b>Linearity</b>	+/- 10g
<b>Calibration</b>	Digital Auto Calibration
<b>Tare Range</b>	Tare Full Capacity
<b>Dimensions</b>	7" <sup>3</sup> / <sub>8</sub> (w) x 9" <sup>1</sup> / <sub>2</sub> (L) x 1" <sup>7</sup> / <sub>8</sub> (h)
<b>Warranty</b>	30 year Warranty



© Myweigh Scale Company All Rights Reserved



# über™ alum

Brushed Aluminum Kitchen Scale

Balance de cuisine en Aluminium Brossé

Abgebürstetes Aluminium-Küchenwaage

5000g x 1g Capacity



**PLEASE READ INSTRUCTIONS  
CAREFULLY BEFORE OPERATING.**

## POWER SUPPLY

4 x 1.5volt AAA batteries. Space located under the scale.

Batteries need to be replaced when "⚡" appears on the display.

## OPERATION

1. Press



The scale will display



then start at



2. Place the food on the scale

The weight will appear on the display.

3. Press



to switch from grams (g) to ounces (oz).

## TARE FUNCTION

1. Once the scale is on, place a container on it.

LCD will display the weight.

2. Press



and the LCD will display



2. You can now weight the food that you will place in the container.

**MANUAL OFF** Press



for 3 seconds

